**16/04/2021**

18/04/2021 to 02/05/2021

| | | Su | Mo | Tu | We | Th | Fr | Sa | Su | Mo | Tu | We | Th | Fr | Sa | Su | Mo |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 01 | 02 | 03 |
| 121_2021 | TANDRAGEE 275/110KV S/S - MAINTENANCE ON IBTX 1 & ASSOC. EARTHING TX | | | | | | | | | | | | | | | | |
| 125_2021 | NEWTOWNARDS MAIN S/S - MAINTENANCE ON TX 1 & ASSOC. EARTHING TX | | | | | | | | | | | | | | | | |
| 150/2021 | COOLKEERAGH 275KV S/S-COOLKEERAGH-MAGHERAFELT 'A' CCT - HOT SPOT REPAIRS | | | | | | | | | | | | | | | | |
| 148_2021 | COOLKEERAGH - MAGHERAFELT 'A' CCT - MAINTENANCE ON D/C TOWERS | | | | | | | | | | | | | | | | |
| 152_2021 | HANNAHSTOWN 110KV S/S - CLAMP MODIFICATIONS & REPAIRS ON ISOLATOR | | | | | | | | | | | | | | | | |
| 003_2021 | Coolkeeragh 14H0 14H3 EH14 LMR-A CVT | | | | | | | | | | | | | | | | |
| 153_2021 | HANNAHSTOWN 110KV S/S - REPLACE ISOLATORS & EARTH SWITCH | | | | | | | | | | | | | | | | |
| PL067/2021 | DUNGANNON MAIN S/S - PROTECTION TRIP TESTING OF MESH CORNER 4 | | | | | | | | | | | | | | | | |
| PL069/2021 | BALLYLUMFORD 275kV S/S - PROTECTION TRIP TESTING OF CIRCUIT BREAKER | | | | | | | | | | | | | | | | |
| PL068/2021 | DUNGANNON MAIN S/S - PROTECTION TRIP TESTING OF MESH CORNER 7 | | | | | | | | | | | | | | | | |
| PL070/2021 | BALLYLUMFORD 275kV & 110kV S/S - PROTECTION TRIP TESTING OF IBTX '2' | | | | | | | | | | | | | | | | |
| PL071/2021 | DRUMNAKELLY MAIN - PROTECTION TRIP TESTING OF TAMNAMORE 'A' CCT | | | | | | | | | | | | | | | | |
| PL072/2021 | BALLYLUMFORD 275kV S/S - PROTECTION TRIP TESTING OF CIRCUIT BREAKER | | | | | | | | | | | | | | | | |
| PL073/2021 | DRUMNAKELLY MAIN - PROTECTION TRIP TESTING OF TAMNAMORE 'B' CCT | | | | | | | | | | | | | | | | |